


CPH Chromit travellers

CPH = Chrome Plated Head

During draw-twisting the stress on the yarn contact area is extremely high. In case of damages (notching), fibril breaks may occur.

Such damages can be prevented by using travellers with chrome-plated, wear resistant yarn contact area.



For the application of Nylon travellers for coarse filaments we recommend Steeltex travellers (see pages 80, 81).