

Traveller inserting and removing tools

Clix

- For inserting (loose) and removing the following travellers:
 - C-shaped
 - Orbit
 - SU
 - J and HZ (light)



Outy

- For removing C-shaped and Orbit travellers
- Removed travellers are collected in the handle

Type	Traveller type
101	Flange 1 (3.2 mm) High-performance travellers
102	Flange 2 (4.0 mm) High-performance travellers
103	Orbit travellers



RL pincers

- For inserting and removing heavy J and HZ travellers made of steel and Nylon

For steel travellers:

- HZ 9,5 / 10,3 / 11,1 / 16,7
- J 11, 1 / 17,4

For Nyltex travellers

- HZ 16,7 / 25,4

